Stormwater Harvesting,

You Can't Set and Forget!


Mahnoush Najmi Process & Operations Engineer Optimal Stormwater

Omid Sayar Process & Operations Engineering Manager Optimal Stormwater

June 2023


Stormwater Harvesting Scheme Overview





Stormwater Harvesting Scheme – Objectives






Stormwater Harvesting Scheme – Proactive Approach










			1 Surt		K. H. M. S		
		Service Che	cklist	Service Report	Serviced and inspected by : A. Ghaemi, M. Najmi Date: September 2022	Reviewed by : O. Sa	
		Checked Item	Status		Comments	General Stat	
Existing Document Review	ASSESS	Lid & Key Hole	50003		comments		
Aisting Document Review	AJJLJJ	Permeable Filter		_		твс	
		Overall Condition		_		i inc	
		Lid Condition	In good condition				
		Pipe Work	No damage or leakage				
		Sedimentation Level	No data sheet	Pump Well was inspected.		No action rec	
		Level Sensor/Transmitter	Operational				
		Isolation Valve	Not found				
eatment and Storage Condition		Controller Mode	Off				
		Alarms	No alarm				
Assessment		Pressure (kPa)	No pressure sensor	-			
Assessment		Flow	5m3/hr	-			
		P1	Shisyni	_			
			-	General check has been done.		No action rea	
		Current (A) P2	-	_			
		P3	-	_			
	the set of the set of the	Noise/ Vibration	Ok				
		Level Switche	Not checked	7			
oment and Control Condition	A CARLES AND A CAR	Pipe Work	No damage or leakage	1			
	A BAR AND A	Sensor Condition	Operational				
Assessment	A CALLER AND	Tubes and Wiring	No damage	General check has been done.		No action re	
Assessment		Overall Condition	Acceptable			no occorre	
		Corrosion/Leakage	No damage or leakage		4. The data is an encoded within the COADA	Antine Deer	
		Data Logger	Non-operational	General check has been done.	1- The data is not recorded within the SCADA.	Action Req	
		Meter Reading (m3)	-				
		Access/Ladder	Heavy Ilids		1- Tank has leakage and should be darined to be		
		Pipe Work	Maintenance Required		checked through confined space entry.		
		Level Sensor/Transmitter	Operational	General check has been done.		Action Req	
Water Palance Medalling		Sedimentation Level	No data sheet	1	2- The outlet pipe of the tank should be thoroughly examined once the tank is emptied.		
Water Balance Modelling		Overall Condition	Unacceptable	-	examined once the tank is emptied.		
		Mode	Off				
		Controller Alarms	No alarm	-			
		Pressure (kPa)	0.3kpa	-			
				_			
		Flow	-		1- The upstream of the suction coming from the		
		P1	-	General check has been done.	storage tank should be checked as the pumps	Action Req	
		Current (A) P2	-		currently cannot be primed.		
		P3	-				
Water Quality Analysis		Noise/ Vibration	Ok	7		(
Water Quality Analysis		Pipe Work	Maintenance Required	1			
		Overall Condition	Acceptable	General check has been done.		No action rea	
				General check has been done.		No action rec	
		Mode	Auto		1- Throughout the audit process, the screen was		
		Controller Pressure Guage (kPa)	Not found		found to be constantly in backwash. Consequently,		
		Tube & Wiring	No damage		the filter was diassembles, cleaned and		
	E SUIT	Manual backwash	Non-operational	General check has been done.	reassembled. Afterwards, while testing the system	Action Requ	
		Piping	Maintenance Required		and with the screen being in filter mode, it was noticed that leakage is happening in the bottom half of the screen.		
	The second se	Lamps	Maintenance Required	1			
	1 ILIC	Alarms	Lamp alarm	-	1- through the sudit process it was indicated that		
		Sleeves	Not checked	General check has been done.	one of the lamps had been burnt out and should	Action Reg	
	and a start and a start a star	ř		General check has been done.		ACTION Req	
		Piping	No damage or leakage	4	be replaced.		
		Controller	Operational				
		Corrosion/Leakage	No damage or leakage				
		Data logger	-	General check has been done.	1- The data is not recorded within the SCADA.	Action Requ	
		Motor reading (m2)	0912m2		1		

Meter reading (m3)

9812m3




						Asset List							
	Assets Details					ASSECTISC							
No.	Description	Asset ID	Location	Manufacturer	Туре	Model	Capacity/Size	Control	Installation Date	Overall Condition	Criticality	Approximate Value	Expected Life Span
1	Hydrofilter	HF-101	Pre-Treatment	Humes	Hydrofilter	HF1000	твс	твс	2012	TBC	Very Important	\$ 100,000.00	30 yrs
2	Pump Well	PW-101	Pre-Treatment	TBC	Concrete	N/A	4m3	Control Panel	2012	Acceptable	Very Important	\$ 40,000.00	30 yrs
3	Transfer Pump	P-101	Pre-Treatment	Grundfos	Submersible Pump	Unilift-KP-250-A-1	Unknown	Control Panel	2012	Acceptable	Important	S 1,000.00	5-7 yrs
4	Turbidity Meter	AT-101	Pre-Treatment	Observator Instruments	Turbidity Probe	ANALITE NEP9000 Series	400NTU	Control Panel	2012	Acceptable	Important	\$ 1,000.00	10 yrs
5	Water Meter	FE-101	Treatment Room	AVFI	Electromagnetic Water Meter	EvoQ4	TBC	Control Panel	2012	Minor Defects	Important	\$ 2,000.00	10 yrs
6	Raw Water Storage Tank	T-101	Storage Tank	TBC	Underground Tank	TBC	300kL	Control Panel	2012	Major Defects	Very Important	\$ 100,000.00	25 yrs
7	Irrigation Pumps	P-1012 A,B	Treatment Room	Grundfos	Vertical Multistage Pump	CRE15-07 A-F-A-E-HQQE	17m3/h 5.50kW	Grundfos Control Panel	2012/2022	Minor Defects	Important	\$ 3,000.00	5 -7 yrs
8	Pressure Tank	PV-101	Treatment Room	Grundfos	Cylindrical	GT-D-80V	80L/ 10bar/ 90°C	TBC	2012	Acceptable	Important	\$ 500.00	10 yrs
9	Self-Cleaning Filter	F-101	Treatment Room	Triangle Filters	Screen Filter	M100-1500	200 microns	Switch Box	2012	Minor Defects	Very Important	\$ 10,000.00	5 yrs
10	UV Disinfection	UV-101	Treatment Room	ProMinent Systems	Duicodes	TBC	твс	Dulcometer	2012	Minor Defects	Very Important	\$ 5,000.00	15 yrs
11	Water Meter	FE-102	Treatment Room	Triangle Filteration & Irrigation	Flanged Water Meter	TBC	твс	N/A	2012	Minor Defects	Important	\$ 1,000.00	10 yrs












Detailed Information – Site Documentation





29/12/2020


29/01/2021

1/03/202

Arash

Arash

Operation Management Information – Water Quality Data






Turbidity (NTU) NHMRC, 2009 Stormwater reuse

Sampling Location	Apr-21	May-21	Jun-21	Jul-21	Aug-21	Sep-21	Oct-21	Nov-21	Dec-21	Jan-22	Feb-22	Mar-22	Apr-22	May-22	Jun-22	Jul-22	Aug-22	Sep-22	Oct-22	Nov-22
Alexandria Oval	0.7	0.9	0.6	0.4	1.04	1.2	0.5	0.5	1.4	0.8	0.7	1	2.9	3	1.6	1.6	1.7	1.4	1.9	1.8
Barcom Park	0.3	0.7	0.7	0.2	0.2	0.2	< 0.1	0.8	1.5	0.1	0.1	0.5	0.1	1	0.8	0.1	0.9	0.8	0.9	0.8
Beare Park	2.3	1.7	2.4	1.8	6.4	2.9	1.4	1.5	3.8	12.4	9.5	1.5	17.3	19	3.4	14.8	3.3	3.9	4.1	3.9
Corning Park	34.7	21	13	1.6	1.2	1.2	4	2.7	4.5	3.9	3.5	3	5.6	6.5	2.8	26.1	2.5	2.3	2.1	1.8
Crown Park	2.3	1.9	2	2.5	2	2.5	2.2	0.6	0.75	7.6	1.8	1.1	2.8	2.2	2.5	1.2	2.3	2.4	1.7	1.5
Harmony Park	2.1	2.4	3.5	0.3	0.6	0.7	2	1.7	1.9	2.7	2.5	1.7	2	2.5	1.8	1	1.9	2	1.9	1.7
Harold Park	0.5	0.9	0.7	0.5	0.3	0.07	0.6	1.2	1.2	1.7	1.5	1.2	1.9	2.6	1.1	0.7	1	1.1	1.6	1.4
Lilian Fowler Reserve	0.8	1	1.9	0.8	2.6	2.1	2.6	1.1	1.2	0.5	0.5	1	0.5	1	1		1.1	1	1.2	1.1
Mary O'Brien Reserve	54.4	4.5	4.2	1.5	2.6	2.1	1.1	NA	1.8	1.4	0.5	0.8	6.3	4.5		0.7	1.2	1.7	2.1	2
Nuffield Park	0.4	0.4	0.4	3.2	1.5	2.1	3.1	2.1	2.3	4.3	1.1	1.5	4.8	5	4.5	7.4	4.6	5.2	6.1	5.1
Paddington Reserve	0.2	0.9	0.8	<0.1	<0.1	<0.1	0.2	0.1	0.25	5	0.15	0.85	1.5	1.2	0.65	0.3	0.7	0.8	0.5	0.4
Peace Park	0.1	0.7	1.5	<0.1	< 0.1	0.05	< 0.1	0.8	1.1	0.1	0.3	0.5	0.4	0.85	0.85	0.2	0.9	0.8	0.9	0.8
Sydney Park	0.1	0.7	1.5	<0.1	<0.1	0.05	<0.1	0.8	1.1	0.1	0.3	0.5	0.4	0.85	0.85	0.2	0.9	0.5	0.6	0.5
Pirrama Park	NA																			
Prince Alfred Park	1.8	1.8	1.1	47	1	NA	2.5	1.1	1.5	0.6	1.5	0.5	18.6	12.5	1.5	0.2	1.6	1.4	1.5	1.2
Solander Park	2	2.3	2.8	4	3.5	3.2	5.5	1.2	5.4	7.5	6.5	1.24	5.2	3.5	1.1	4.7	1	1.1	2.1	1.8
St. James	7.3	1.6	4.8	1.3	1.3	2.7	2.4	2.4	3	1.2	1.1	2.1	2.1	1.8	2.3	5	2.4	2.7	3.1	2.8
Trurruwul Park	0.8	0.4	0.6	60.2	<0.1	1.5	0.6	0.25	2.35	0.6	1.7	1	0.7	0.85	3.4	1.3	3.3	3.7	3.1	2.8
Waterloo Oval	0.1	3.2	5.6	0.8	3.8	4.1	1.3	2.18	3.1	2	2	1.5	3.2	2.9	10.5	17.1	10.1	7.1	3.6	2.5
Redfern Oval	395	34	36	107	95.1	93	538	11.5	6.5	397	410	3.5	238	115	12	3150	12.1	8.5	5.1	5.4
Erskineville Oval									0.25	0.3	0.4	0.9	0.7	0.9	1.9	0.6	1.8	1.2	7.4	5.1


Limit 25



High Level Information – Daily Water Supply




Non-Potable %





Stormwater Harvesting Scheme Overview







Thank you for your attention! 🙂